



Photo 1 – View of accident airplane from front (courtesy of FAA)



Photo 2 – View of bottom of right wing (note damage to wing strut and inboard wing) (courtesy of FAA)