

WPR24LA140

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane from the right. (Courtesy of the pilot.)



Photograph 2 - View of substantial damage to the right wing. (Courtesy of the pilot.)



Photograph 3 - View of substantial damage to vertical stabilizer. (Courtesy of the pilot.)