

WPR24LA143

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane lining up for takeoff (Courtesy of North Tooele Fire Department)



Photograph 2 - Airplane after accident (Courtesy of North Tooele Fire Department)