

WPR24LA159

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, forward right side view. (Courtesy of the FAA)



Photograph 2 - Accident site, right side view. (Courtesy of the FAA)



Photograph 3 - Accident site, left side view. (Courtesy of the FAA)



Photograph 4 - Accident site, forward left side view. (Courtesy of the FAA)