

WPR24LA162

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right side of airplane. (Courtesy of pilot)



Photograph 2 - View of damage to left wing. (Courtesy of pilot)



Photograph 3 - View of damage to right wing. (Courtesy of pilot.)