

WPR24LA163

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to right wing. (Courtesy of pilot)



Photograph 3 - View of damage to empennage. (Courtesy of pilot)