

WPR24LA165

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of aircraft from its right side. (Courtesy of pilot.)



Photograph 2 - View of aircraft from aft. (Courtesy of pilot.)



Photograph 3 - View of damage to upper wing. (Courtesy of pilot.)