

WPR24LA167

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of accident airplane (Courtesy of FAA)



Photograph 2 - View of fuselage damage (Courtesy of FAA)



Photograph 3 - View of left wing damage (Courtesy of FAA)