

WPR24LA177

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Wreckage (Courtesy of Pilot)




Photograph 2 - Runway Marks and Wreckage (Courtesy of Pilot)




Photograph 3 - Tailwheel Assembly at Accident Site (Courtesy of Pilot)



Photograph 4 - Tailwheel Assembly (Courtesy of Pilot)



Photograph 5 - Tailwheel Assembly Damage (Courtesy of Pilot)



Photograph 6 - Tailwheel Assembly Damage Closeup (Courtesy of Pilot)