

WPR24LA207

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane from above (Courtesy of local law enforcement)



Photograph 2 - View of left wing damage (Courtesy of local law enforcement)