

WPR24LA214

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N6793K at the recovery site, right side view.



Photograph 2 - Left side view.



Photograph 3 - Front view.



Photograph 4 - Wings and supports.