

WPR24LA218

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Right Side View of Accident Airplane (Courtesy of Law Enforcement)**



**Photograph 2 - Front View of Airplane with Damaged Left Wing (Courtesy of Law Enforcement)**