

WPR24LA221


INVESTIGATION PHOTOGRAPHS




Photograph 1 - View of the airplane from forward. (Courtesy of Sheriff's Department.)



Photograph 2 - View of substantial damage to aft fuselage. (Courtesy of Sheriff's Department.)



Photograph 3 - A screenshot of the accident site location. (Courtesy of Sheriff's Department.)



Photograph 4 - Topography surrounding accident site.