

WPR24LA222

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wing damage (Courtesy of pilot)



Photograph 2 - Left elevator damage (Courtesy of pilot)



Photograph 3 - Fuselage damage (Courtesy of pilot)