

WPR24LA224

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane from right. (Courtesy of pilot.)



Photograph 2 - View of airplane from left. (Courtesy of pilot.)



Photograph 3 - View of substantial damage to empennage. (Courtesy of pilot.)