



Photo 1 – View of accident airplane from left wing; note damage outboard and to forward fuselage (courtesy of FAA)



Photo 2 – Left wing outboard leading edge (courtesy of FAA)