

WPR24LA239

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Photo of all helicopter debris at the site (Courtesy of the Operator)



Photograph 2 - Forward fuselage photo of helicopter at the site (Courtesy of the Operator)



Photograph 3 - Top view of the helicopter at the site (Courtesy of the Operator)