

WPR24LA242

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of substantial damage to the left wing. (Courtesy of pilot.)



Photograph 2 - View of substantial damage to the left wing. (Courtesy of pilot.)



Photograph 3 - View of substantial damage to the left wing. (Courtesy of pilot.)