

WPR24LA243

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of accident helicopter with view of damage to the main rotor blades
(Courtesy of operator)**



Photograph 2 - View of helicopter laying on its left side, with damage to lower fuselage and missing left skid (Courtesy of operator)