

WPR24LA244

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane on Runway (Courtesy of Airport Operations)



Photograph 2 - Damage to Left Wing and Stabilizer (Courtesy of Airport Operations)