

WPR24LA246

INVESTIGATION PHOTOGRAPH



Photograph 1 - View of right wing damage (Courtesy of pilot)