

WPR24LA248

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of accident airplane during exam



Photograph 2 - Front / left view of accident airplane during exam



Photograph 3 - Right side view of accident airplane during exam



Photograph 4 - Front view of accident airplane engine during exam