

WPR24LA251

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the helicopter from the front. (Courtesy of the FAA.)



Photograph 2 - View of the helicopter from aft. (Courtesy of the FAA.)



Photograph 3 - View of substantial damage to tailboom. (Courtesy of the FAA.)