

WPR24LA253

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side view of accident airplane



Photograph 2 - View of right aileron damage