


WPR24LA254

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Side View of Airplane (Courtesy of Law Enforcement)



Photograph 2 - Right Side View of Airplane (Courtesy of Law Enforcement)



Photograph 3 - Overall View of Main Wreckage (Courtesy of Law Enforcement)



Photograph 4 - View of Right Engine (Courtesy of Law Enforcement)