

WPR24LA256

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side view of accident airplane (Courtesy of airport operations)



Photograph 2 - View of rudder damage