

WPR24LA258

ONSITE INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, main wreckage. (Courtesy of CMA Airport Operations)



Photograph 2 - Accident site, main wreckage. (Courtesy of CMA Airport Operations)



Photograph 3 - Accident site, main wreckage. (Courtesy of CMA Airport Operations)



Photograph 4 - Accident site, propeller damage. (Courtesy of CMA Airport Operations)



Photograph 5 - Accident site, runway impact marks. (Courtesy of CMA Airport Operations)



Photograph 6 - Accident site, runway impact marks. (Courtesy of CMA Airport Operations)



Photograph 7 - Accident site, runway impact marks. (Courtesy of CMA Airport Operations)