

WPR24LA259

ONSITE INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, main wreckage. (Courtesy of the FAA)



Photograph 2 - Accident site, main wreckage. (Courtesy of the FAA)



Photograph 3 - Accident site, right wing root area. (Courtesy of the FAA)



Photograph 4 - Accident site, fuel selector valve. (Courtesy of the FAA)



Photograph 5 - Accident site, separated engine components. (Courtesy of the FAA)



Photograph 6 - Accident site, main wreckage. (Courtesy of the FAA)