


WPR24LA259

ONSITE INVESTIGATION PHOTOGRAPHS-AP OPS



Photograph 1 - Accident site, fwd right view of the main wreckage. (Courtesy of Airport Ops)



Photograph 2 - Accident site, aft left view of the main wreckage. (Courtesy of Airport Ops)



Photograph 3 - Accident site, aft right view of the main wreckage. (Courtesy of Airport Ops)



Photograph 4 - Accident site, left wing and cabin area. (Courtesy of Airport Ops)



Photograph 5 - Accident site, forward fuselage view. (Courtesy of Airport Ops)