

WPR24LA260

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site. (Courtesy of pilot)



Photograph 2 - Propeller hub. (Courtesy of pilot)



Photograph 3 - Root end of recovered blade. (Courtesy of pilot)