

WPR24LA272

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to fuselage. (Courtesy of pilot)



Photograph 2 - View of fuselage damage into cabin. (Courtesy of pilot)