

WPR24LA274

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Sailplane left wing damage (courtesy of pilot)



Photograph 2 - Sailplane tailcone damage (courtesy of pilot)