

WPR24LA279

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane from forward left. (Courtesy of pilot.)



Photograph 2 - View of airplane from left. (Courtesy of pilot.)



Photograph 3 - View of substantial damage to fuselage structure. (Courtesy of pilot.)