

WPR24LA282

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the damage to the fuselage and wings (Courtesy of operator)