

WPR24LA286

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left wing impact damage and parked trailer. (Courtesy of the pilot.)



Photograph 2 - Left wing damage and parked trailer. (Courtesy of the pilot.)



Photograph 3 - Airplane aft fuselage damage. (Courtesy of the pilot.)



Photograph 4 - Airplane aft fuselage damage. (Courtesy of the pilot.)



Photograph 5 - Airplane aft fuselage damage. (Courtesy of the pilot.)



Photograph 6 - Airplane aft fuselage damage. (Courtesy of the pilot.)