

WPR24LA296

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane stored at airport




Photograph 2 - View of damaged right lower fuselage and engine compartment



Photograph 3 - View of left side instrument panel



Photograph 4 - View of right side instrument panel



Photograph 5 - View of airplane operation checklist



Photograph 6 - View of fuel selector and caption "Both tanks on for takeoff and landing."