

WPR24LA310

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, main wreckage. (Courtesy of Redlands Police Department)



Photograph 2 - Accident site, right wing. (Courtesy of Redlands Police Department)



Photograph 3 - Accident site, empennage. (Courtesy of Redlands Police Department)