

WPR25FA020

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident site.



Photograph 2 - View of layout during examination.



Photograph 3 - View of engine during examination.