

WPR25LA018

INVESTIGATION PHOTOGRAPHS




Photograph 1 - View of airplane from the left. (Courtesy of the pilot.)



Photograph 2 - View of airplane from the right. (Courtesy of the pilot.)



Photograph 3 - View of substantial damage to the empennage. (Courtesy of the pilot.)



Photograph 4 - View of substantial damage to the left wing. (Courtesy of the pilot.)