

11/11/2024

Michael Ormerod
Principal Maintenance Inspector (PMI)
Scottsdale Flight Standards District Office
AFG-SDL-FSDO-07

Scottsdale, AZ 85255

RE: Request for Information Concerning an Occurrence Sheet

Owner/PIC:

Jonathan Rocha [REDACTED]

No other occupants at time of incident

Maintenance Provider:

Eagle Air, Philip [REDACTED]

Local Time of Occurrence:

1620 (MST)

Weather Briefing Source:

ForeFlight

Weather Conditions:

Visibility > 10 SM, Skies Clear below 12,000, don't remember exact wind direction & speed, but it was gusty. No icing conditions.

Persons on Board:

One. Jonathan Rocha (PIC/Owner)

Purpose of Flight:

Personal use. To further assess "odd" mixture settings during climb phase a couple of days prior to incident date. See Written Statement dated 11/11/2024 for more information.

PIC # of Hours in M&M:

67.0

PIC # of Hours in Past 90 Days:

36.7

PIC # of hours in Past Year:

130.6

PIC Total # of Hours:

208.6

PIC Date of Regulatory Ride:

Flight Review 11/17/2023

Date of Last Annual Inspection:

6/27/2024

Current Location of Aircraft:

Prescott Regional Airport (KRPC), Cutter Aviation Ramp

Copy of Airman Certificate:

Shared Dropbox Link to Cert

Copy of Current Medical Cert:

Shared Dropbox Link to Cert

Copy of Airworthiness Cert:

Shared Dropbox Link to Cert

Copy of Aircraft Registration:

Shared Dropbox Link to Cert

Copy of Entry for Last Annual:

Shared Dropbox Link to Cert

Copy of Last Maintenance Performed:

Shared Dropbox Link to Cert

Copy of MX following occurrence:

NONE

[REDACTED]
11/11/2024