

NATIONAL TRANSPORTATION SAFETY BOARD • PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT Use this form (Form 6120.1) to report civil and public aircraft accidents and incidents**BASIC INFORMATION****Accident/Incident Location**Nearest City/Place: Prescott State: AZZIP: 86301 Country: USALatitude: 34.651066 Longitude: -112.427872

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/TimeDate: 11/07/2024 Local Time: 06:42
mm/dd/yyyy HH:MMTime Zone: MSTCollision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None**AIRCRAFT INFORMATION**Registration Number: N679ERManufacturer: CessnaModel: C172SSerial Number: 172S12754Year of Manufacture: 2,021Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Original Design ☐ Kit/Plans

Make: _____

- ☒
- IFR-Equipped and Certified
-
- ☐
- Commercial Space Flight
-
- ☐
- Unmanned Aircraft

Maximum Gross Weight: 2,550 lbs.Weight at Time of Accident/Incident: 2,283 lbs.Number of Seats: 3 Flight Crew Seats: 2Cabin Crew Seats: _____ Passenger Seats: 1Number of Engines: 1**Category of Aircraft**
(Select one)

- ☒
- Airplane
-
- ☐
- Balloon
-
- ☐
- Blimp/Dirigible
-
- ☐
- Glider
-
- ☐
- Gyroplane
-
- ☐
- Helicopter
-
- ☐
- Powered Lift
-
- ☐
- Rocket
-
- ☐
- Ultralight
-
- ☐
- Unknown

Type of Airworthiness Certificate
(Check all that apply)

- | | |
|---|---|
| Standard | Special |
| ☒ Normal | ☐ Restricted |
| ☐ Aerobatic | ☐ Limited |
| ☐ Balloon | ☐ Provisional |
| ☐ Commuter | ☐ Special Flight |
| ☐ Transport | ☐ Experimental |
| ☐ Utility | ☐ Special Light-Sport |
| | ☐ Experimental Light-Sport |
| ☐ Certificate of Authorization or Waiver (COA) | |
| ☐ None ☐ Unknown | |

Landing Gear
(Check all that apply)

- | | |
|---|------------------------------------|
| ☐ Retractable | ☐ High Skid |
| ☒ Tricycle | ☐ Skid |
| ☐ Tailwheel | ☐ Ski/Wheel |
| ☐ Emergency Float | ☐ Hull |
| ☐ Float | ☐ Ski |
| ☐ Amphibian | |
| ☐ Other Launch/Recovery System | |
| ☐ None | ☐ Unknown |

Engine Type (Select one)

- | | |
|--|-------------------------------------|
| ☒ Reciprocating | ☐ Liquid Rocket |
| ☐ Turbo Shaft | ☐ Solid Rocket |
| ☐ Turbo Prop | ☐ Hybrid Rocket |
| ☐ Turbo Jet | ☐ None |
| ☐ Turbo Fan | ☐ Unknown |
| ☐ Electric | |

Fuel System Type (Reciprocating)

- ☐
- Carburetor
- ☒
- Fuel Injected

Engine	Engine Manufacturer	Engine Model/Series	Engine Serial Number	Date of Mfg. (mm/dd/yyyy)	Rated Power ☒ Horsepower or ☐ Lbs. of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Lycoming	IO-360-L2A	L-38295-51E	03/05/2024	180	2,701	0	295
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐
- 100-Hour
-
- ☐
- AAIP
-
- ☐
- Annual
-
- ☒
- Continuous Airworthiness
-
- ☐
- Condition Inspection
-
- ☐
- Unknown

Date of Last Inspection: 11/06/2024
mm/dd/yyyyAirframe Total Time: 2,699.5 hrs

Hours measured at (Select one)

☒ Last Inspection ☐ Time of Accident/Incident**Type of Maintenance Program (Select One)**

- ☐
- Annual
-
- ☐
- Conditional (Amateur-built only)
-
- ☒
- Manufacturer's Inspection Program
-
- ☐
- Other Approved Inspection Program
-
- ☐
- (AAIP) Continuous Airworthiness
-
- ☐
- Other, specify: _____

Description of Fire Extinguishing System

- ☒
- None
-
- ☐
- Specify: _____

Additional Equipment

- ☒
- ADS-B
-
- ☐
- Airframe Parachute
-
- ☐
- Angle of Attack Indicator
-
- ☒
- Autopilot
-
- ☐
- Autopilot/FMS, Model: _____
-
- ☐
- Coupled Flight Director
-
- ☐
- Data Recorder
-
- ☐
- Device Stall Warning System
-
- ☒
- Electronic Flight Bag or Handheld Device
-
- ☒
- Electronic Multifunction Display
-
- ☒
- Electronic Primary Flight Display
-
- ☒
- Flight Management System

- ☐
- Handheld GPS
-
- ☐
- Heads Up Display
-
- ☐
- Night Vision Goggles
-
- ☐
- Onboard Weather
-
- ☐
- Primary Flight Display
-
- ☐
- SAS, Number of Axes: _____ Model: _____
-
- ☐
- Satellite Tracking Device
-
- ☒
- Stall Warning System
-
- ☐
- Video Recording Device
-
- ☐
- Wire Strike Detection
-
- ☐
- Wire Strike Protection
-
- ☐
- Other, Specify: _____

ELT Installed: ☒ Yes ☐ No If Yes:ELT Manufacturer: ARTEXModel or Part No.: 406ELTTSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☒ C126 (406 MHz)Was ELT still mounted in aircraft? ☒ Yes ☐ NoWas ELT still connected to antenna? ☒ Yes ☐ NoDid ELT activate? ☐ Yes ☒ NoIf activated: Did ELT aid in locating aircraft? ☐ Yes ☐ NoIf not activated: Indicate Reason: ☐ Impact Damage☐ Fire Damage ☐ Battery Expired/Damaged ☒ UnknownPropeller 1 ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground AdjustableManufacturer: McCauleyModel: 1A170EPropeller 2 ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Embry-Riddle Aeronautical University

Fractional Ownership Aircraft:

☐ Yes☐ NoCity: PrescottState: AZZIP: 86301Country: USA**Operator of Aircraft**☒ The Operator is also the Registered Owner☒ Same address as Registered Owner

Name: _____

Doing Business As: _____

City: _____

State: _____

Air Carrier/Operator Designator (4-character code): _____

ZIP: _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☒ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
 Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
☐ FAR 450
☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
☐ Public Aircraft (Select one)
 ☐ Armed Forces
 ☐ Federal
 ☐ State
 ☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137 (Select one)

- ☐ Aerial Application ☐ Firefighting
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry ☐ Unknown

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Prescott Regional / Ernest A Love Field

Distance From Airport Center: _____ sm.

Airport Identifier: KPRC

Direction From Airport: _____ degrees true

Proximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 5,045.00 ft. MSL**Runway Information**

Runway ID: _____ Length: _____ ft. Width: _____ ft.

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Ice ☐ Snow
☐ Concrete ☐ Gravel ☐ Macadam ☐ Water
☐ Dirt ☐ Helideck ☐ Metal/Wood ☐ Unknown
☐ Elevated Heliport ☐ Helistop ☐ Off-site landing area

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☒ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Crosswind ☐ Aborted Landing (after touchdown)
☐ Unknown

IFR Approach (Check all that apply)☒ None

- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR ☐ Unknown
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling

VFR Approach (Check all that apply)☒ None

- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION**"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident**

☐ Captain ☐ First Officer ☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☒ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Tia

City of Residence: Prescott

Middle Initial: _____

State: AZ ZIP: 86301

Last Name: Tabet

Country: USA

Age at time of Accident/Incident: 22

Date of Birth: 2002 (mm/dd/yyyy)

Certificate Number:

Degree of Injury

☒ None ☐ Serious
☐ Unknown ☐ Fatal
☐ Minor

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☒ Right ☐ Rear
☐ Center ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Supplemental Restraint, specify: _____

Inflatable Restraints

☐ Not Installed
☒ Installed
☒ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☒ Flight Instructor ☒ Commercial
☐ US Military ☐ Private ☐ Recreational
☐ Airline Transport ☐ Foreign ☐ Sport
☐ Student ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3 ☐ Unknown
☒ Class 1 ☐ BasicMed
☐ Class 2 ☐ Driver's License (Sport Pilot only)

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☒ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

04/15/2024
 mm/dd/yyyy

Medical Certificate Limitations

Must use corrective lenses to meet vision standards at all required distances

Medical Certificate Special Limitations**Personal Flight Equipment** (Check all that apply)

☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ Personal locator beacon(s) (PLB) ☐ Fire resistant gloves
☐ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

03/20/2024
 mm/dd/yyyy

Flight Review Aircraft

Make: Diamond

Model: DA-40

Airplane Rating(s)
(Check all that apply)

☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)
(Check all that apply)

☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)
(Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)
(Check all that apply)

☐ None ☒ Instrument Airplane
☒ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multiengine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered lift ☐ Sport

Type Ratings and Applicable Logbook Endorsements**Student Endorsements** (Include dates)

Flight Time (Enter hours for each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air	Multi-engine Rotorcraft	Tail-wheel
						Actual	Simulated					
Total Time	607	546	566	41	46	1	107					
Pilot in Command (PIC)	458	437	437	0	41	1	49					
Time as Instructor	204	204	204	0	18	1	0					
This Make/Model					43	0	0					
Last 90 Days	204	204	204	0	20	0	0					
Last 30 Days	93	93	93	0	5	0	0					
Last 24 Hours	6	6	6	0	0	0	0					

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information.)

Additional Crewmember Information		Seat Occupied	Injury
First Name: _____	City of Residence: _____	☐ Left ☐ Rear ☐ Center ☐ Single ☐ Right ☐ Unknown ☐ Front	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Middle Initial: _____	State: _____ Zip: _____		
Last Name: _____	Country: _____		
Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ Personal locator beacon(s) (PLB) ☐ Fire resistant gloves ☐ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____			
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer		Restraint Type Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown Supplemental Restraint, specify: _____	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No	Total Flight Time at the Time of this Accident/Incident: _____ hrs.		

Additional Crewmember Information		Seat Occupied	Injury
First Name: _____	City of Residence: _____	☐ Left ☐ Rear ☐ Center ☐ Single ☐ Right ☐ Unknown ☐ Front	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Middle Initial: _____	State: _____ Zip: _____		
Last Name: _____	Country: _____		
Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ Personal Locator Beacon(s) (PLB) ☐ Fire resistant gloves ☐ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____			
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer		Restraint Type Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown Supplemental Restraint, specify: _____	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No	Total Flight Time at the Time of this Accident/Incident: _____ hrs.		

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet, if necessary.)

Number of Passengers _____	Seat	Injury	Restraint Type	Inflatable Restraints	Age
Passenger Information First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown Supplemental Restraint, specify: _____	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown

First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Supplemental Restraint, specify: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Supplemental Restraint, specify: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Supplemental Restraint, specify: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point	Time of Departure	Flight Information	Destination	Type Flight Plan Filed
Airport ID: _____ City: _____ State: _____ Country: _____	Time: _____ HH:MM Time Zone: _____	Flight Number: ERU79 Operating as Flight _____	Airport ID: _____ City: _____ State: _____ Country: _____	☐ None ☐ Company VFR ☐ Military VFR ☐ VFR ☐ VFR/IFR ☐ IFR ☐ Unknown Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)				
☐ Certificate of Authorization	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA
☒ None				
Airspace where the accident/incident occurred (Check all that apply)				
☐ Class A	☐ Class G	☐ Military Operations Area (MOA)	☐ Special	
☐ Class B	☐ Demo Area	☐ Airport Advisory Area	☐ Air Traffic Control Area	
☐ Class C	☐ Warning Area	☐ Jet Training Area	☐ Unknown	
☒ Class D	☐ Prohibited Area	☐ TRSA		
☐ Class E	☐ Restricted Area	☐ FAR 93	Altitude of In-Flight Occurrence: _____ ft. MSL	
WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE				
Source of Pilot Weather Information (Check all that apply)		Weather Observation Facility		
☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☐ Automated Report ☒ Electronic Flight Bag-Application: Foreflight ☐ On-Board Weather		Facility ID: <u>KPRC</u> Observation Time: <u>1245 Zulu</u> Time Zone: <u>MST</u> Distance from Accident Site: _____ nm Direction from Accident Site: _____ degrees true		
Basic Conditions		Lowest Cloud Condition		
☒ VMC ☐ IMC ☐ Unknown		Height: _____ ft. AGL ☒ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☐ Day ☐ Night ☐ Bright Night		
Sky/Lowest Cloud Condition		Ceiling		Light Condition
☒ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial ☐ Unknown ☐ Obscuration ☐ Scattered		☒ None (Clear) ☐ Broken ☐ Overcast ☐ Obscured ☐ Indefinite ☐ Unknown		Ceiling Height: _____ ft. AGL Temperature: <u>-3.00</u> (°C) or _____ (°F) Dewpoint: <u>-9.00</u> (°C) or _____ (°F)
Altimeter Setting:		Wind Direction	Wind Speed	Wind Gusts
<u>30.09</u> (Hg), or _____ (mb)		☒ Variable or _____ Direction: _____ degrees true	☐ Calm ☐ Light and Variable or Speed: <u>5.0</u> kts	☒ Not Gusting or Speed: _____ kts
Type of Precipitation (Check all that apply)		Intensity of Precipitation		Restriction to Visibility (Check all that apply)
☒ None ☐ Drizzle ☐ Freezing Rain ☐ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals		☐ Light ☐ Moderate ☐ Heavy ☐ N/A ☐ Unknown		☒ None ☐ Fog ☐ Blowing Dust ☐ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☐ Unknown
Icing Forecast		Icing Actual		Turbulence (Check all that apply)
Amount: ☒ None Type: ☐ N/A ☐ Trace ☐ Rime ☐ Light ☐ Clear ☐ Moderate ☐ Mixed ☐ Severe ☐ Unknown ☐ Unknown		Amount: ☒ None Type: ☐ N/A ☐ Trace ☐ Rime ☐ Light ☐ Clear ☐ Moderate ☐ Mixed ☐ Severe ☐ Unknown ☐ Unknown		Type: ☒ None Severity: ☐ Light ☐ Clean Air ☐ Moderate ☐ Terrain-Induced ☐ Severe ☐ Convective ☐ Extreme Turbulence
NOTAMS (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:				
IPRC 05/155 PRC RWY 03L THR DISPLACED 361FT. DECLARED DIST: TORA 4396FT TODA 4396FT ASDA 4396FT LDA 4035FT. 2205242023-PERM IPRC 05/156 PRC RWY 21R DECLARED DIST: TORA 4396FT TODA 4396FT ASDA 4396FT LDA 4396FT. 2205242023-PERM IFDC 3/0853 PRC ODP PRESCOTT RGNL - ERNEST A LOVE FLD, PRESCOTT, AZ.				
DIVERSE VECTOR AREA (RADAR VECTORS) ORIG-A ...				
RWY 3L, HEADING AS ASSIGNED BY ATC; REQUIRES MINIMUM CLIMB OF 212 FT/NM TO 7000.				
RWY 3R, HEADING AS ASSIGNED BY ATC; REQUIRES MINIMUM CLIMB OF 204 FT/NM TO 7000.				
RWY 21L, HEADING AS ASSIGNED BY ATC; REQUIRES MINIMUM CLIMB OF 448 FT/NM TO 8300.				

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None
☐ Minor
☒ Substantial
☐ Destroyed
☐ Unknown

Aircraft Fire

- ☒ None
☐ In-Flight
☐ On-Ground
☐ Both Ground and In-Flight
☐ Fire at Unknown Time
☐ Unknown

Aircraft Explosion

- ☒ None
☐ In-Flight
☐ On-Ground
☐ Both Ground and In-Flight
☐ Fire at Unknown Time
☐ Unknown

Description of Damage to Aircraft and Other Property (Use additional sheet, if necessary.)

Outboard leading edge of the right wing contacted metal fence post. Internal rib bent and damaged. Exterior leading edge damaged - dent on leading edge, caused buckling of underside of the wing.

Classifies as a Major Repair - (xxiv) - the splicing of skin sheets

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink.)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

On November 7th, 2024 a 321 Commercial Single training activity, lesson 19, was scheduled for 06:30, authorized by the instructor at 05:54, the student checked in at 06:18, and ramped out at 06:38. The aircraft was parked on Ramp 3, adjacent to the Regional Terminal. The outside temperature was reported at -3 degrees C and the dew point was -9 degrees C. The aircraft had frost on the lift producing surfaces, so after preflight, the crew proceeded to taxi into the deice bay. The crew shut off the engine, and the deice crew sprayed the aircraft down. After deice was completed, the crew started the aircraft back up. In front of the crew, maintenance had positioned another aircraft in the corner and started that engine for a reposition. The student in ERU79 began to taxi, but the instructor noticed that the student did not start the turn soon enough or steep enough to avoid the aircraft in front of them (the maintenance airplane), so the instructor took the flight controls and applied left rudder and brake to turn away from the other aircraft. Once the instructor was clear of the other aircraft, she continued to taxi straight ahead.

Sunrise on 11/7/24 was 6:56am in Prescott AZ. The main overhead ramp light was inoperative, but there was a small light on the side of the building adjacent to the deice bay that was on.

Instructor Statement: While finishing the de-icing procedure at ramp 3, we started the engine and taxied out of the spot, trying to maneuver between a parked plane located in the corner between the terminal limit and the hangar door. SP went too far forward, and IP took control to maneuver out of place. As I turned, the wing hit the side of the fence between ramp three and the terminal. I stopped and parked the plane; maintenance helped with the aircraft and canceled the activity. When de-ice was done, the student went too forward. I thought, as the IP, that we were going too close to the parked plane, so I took control, I tried making a tight turn, but when I looked right at the fence, it looked like the wing was clear of the fence and above it. However, it was not, and the fence had a higher pole at the end of it, which collided with the wing.

Student Statement: After preflight we maneuvered to deice on ramp 3. There was a plane in the corner past the deice bay. When deice was complete, I started up the engine and tried to turn sharp to avoid the plane in the corner who also had their engine running. I did not turn sharp enough and was getting close to the plane, so my instructor took controls. I was not looking at the fence and was more focused on the aircraft in the corner. Once we were clear of the other aircraft, my instructor continued to taxi forward and that is when we hit the fence. I set the parking brake, shut down the engine, and got out of the aircraft.

Mechanic #1 : I was standing looking towards aircraft approximately 25 feet away. I observed student pilot in left seat and flight instructor in right seat. Aircraft started taxiing out and then brakes were applied to conduct a break ops. check. Aircraft continued to taxi with speed at approximately 2-3 knots with a slight turn to the left. Aircraft then straightened out and continued to taxi with wing striking end of fence line on right side wing outboard leading edge. At this time the aircraft came to a complete stop. During incident visibility was dark and poor.

Mechanic #2 : Riddle 76 was parked in the corner between the fence and the maintenance building. I had just started the engine on Riddle 75 in order to taxi to the run-up area. I waited as Riddle 79 taxied in front of me. While taxiing in front of me I saw Riddle 79's right wing come in contact with the fence on the south side of the maintenance area.

OPERATOR/OWNER SAFETY RECOMMENDATION (How could this accident/incident have been prevented?)

- 1: put up low clearance barricade between fence and exit row to prevent taxiing into the fence (already completed)
- 2: fix main light on the ramp to ensure ramp is illuminated.
- 3: prohibit maintenance from maneuvering aircraft in the corner when de-ice operations are happening.
- 4: After de-ice, have de-ice crew lead/signal crew into position to leave the ramp

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on a separate sheet.)Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/ Cycles On Part

_____ Hours

_____ Cycles

Time Since This Part Inspected/Overhauled

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

40.0 Gallons

Fuel Type

☒ 100 Low Lead☐ Automotive☐ Jet A☐ Jet A-1☐ Unleaded AV☐ Other, specify _____

Other Services, if any, prior to departure:

De-ice

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location:

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft.)

Aircraft Registration Number

Manufacturer: _____

Damage to Other Aircraft:

☐ Destroyed☐ Minor☐ Substantial☐ None

Model: _____

Registered Owner of Other Aircraft

Pilot of Other Aircraft

Name: _____

Name: _____

City: _____

City: _____

State: _____ ZIP: _____

State: _____ ZIP: _____

Country: _____

Country: _____

ADDITIONAL INFORMATION (Additional space for answers to any question.)

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE.

I understand that the information provided may be subject to public release.

Date of this report:

11/15/2024

mm/dd/yyyy

Name of Pilot/Operator: _____

Signature: _____

-or- ☐ Check here to electronically sign this document

If a person other than Pilot/Operator is filing this report

Name: Mikayla (Mik) Quesenberry

Title: Director of Aviation Safety

Signature: _____

-or- ☒ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.	Reviewed by NTSB AS Division	Name of Investigator	Date Report Received
WPR25LA032	OAS-WPR	Kathryn Whitaker	November 15, 2024