

WPR25LA033

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to right wing. (Courtesy of airport operations.)



Photograph 2 - View of damage to right wing. (Courtesy of airport operations.)