

WPR25LA040

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, main wreckage. (Courtesy of the Yavapai County Sheriff's Office)



Photograph 2 - Accident site, main wreckage and impact marks. (Courtesy of the Yavapai County Sheriff's Office)



Photograph 3 - Accident site, right side of airplane. (Courtesy of the Yavapai County Sheriff's Office)



Photograph 4 - Accident site, engine cowling and propeller assembly. (Courtesy of the Yavapai County Sheriff's Office)



Photograph 5 - Accident site, left wing. (Courtesy of the Yavapai County Sheriff's Office)



Photograph 6 - Accident site, cabin area. (Courtesy of the Yavapai County Sheriff's Office)