

WPR25LA042

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Substantial Damage of Remos Wing (Courtesy of ERAU)



Photograph 2 - View of Both Aircraft (Courtesy of ERAU)