


WPR25LA044

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, view of the left rear side of the airplane. (Courtesy of Airport Operations)



Photograph 2 - Accident site, view of the left forward side of the airplane. (Courtesy of Airport Operations)



Photograph 3 - Accident site, view of right forward side of the airplane. (Courtesy of Airport Operations)



Photograph 4 - Accident site, view of the right rear side of the airplane. (Courtesy of Airport Operations)