

WPR25LA053

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of accident airplane (Courtesy of Airport Operations)



Photograph 2 - View of fuselage buckling (Courtesy of Airport Operations)



Photograph 3 - View of rudder damage (Courtesy of Airport Operations)



Photograph 4 - View of ice on stall warning (Courtesy of FAA)



Photograph 5 - View of ice on leading edge of wing (Courtesy of FAA)