

WPR25LA061

INVESTIGATION PHOTOGRAPHS



Photograph 1 - The Runway Sign (NTSB Photo)



Photograph 2 - View of the Airplane from the Right (NTSB Photo)



Photograph 3 - View of substantial damage to lower forward fuselage. (Courtesy of the FAA)



Photograph 4 - View of substantial damage to lower forward fuselage. (Courtesy of the FAA)