

WPR25LA066

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, airplane right side view. (Courtesy of Airport Operations)



Photograph 2 - Airplane recovery photo of the left wing. (Courtesy of Airport Operations)



Photograph 3 - Airplane recovery photo of the right wing. (Courtesy of Airport Operations)



Photograph 4 - Accident site, terrain impact marks. (Courtesy of the FAA)