

WPR25LA071

INVESTIGATION PHOTOGRAPHS



Photograph 1 - The airplane at the accident site. (Courtesy of the FAA.)



Photograph 2 - The airplane after removal from the accident site. (Courtesy of the pilot.)



Photograph 3 - The airplane during engine run.



Photograph 4 - Airplane during testing of fuel quantity indicating system.