

WPR25LA073

INVESTIGATION PHOTOGRAPH



Photograph 1 - View of substantial damage to the right wing (Courtesy of FAA)



Photograph 2 - Top view of substantial damage to both wings (Courtesy of FAA)